


Compatibility of 3M™ Air Delivery Units and Headtops

The new welding helmets and faceshields from 3M feature the QRS type of breathing tube (Quick Release Swivel), which enables one-handed connection and release. Older types of breathing tubes (non-QRS) can be used by adding the helmet breathing tube adapter (part no 53 35 05).

The new type of QRS breathing tubes are also approved for 3M™ Speedglas™ Welding Helmet Series 9000 and 3M™ Speedglas™ Protective Visors by adding a specific helmet breathing tube adapter (part no 53 35 06).



* The Speedglas welding helmet series 9100 replaces most of the Speedglas welding helmet series 9000. Accessories and spare parts for the 9000 helmets will be available for 3-5 years.

** The protection class of Speedglas welding helmet 9100 FX Air is reduced to TH2 when the adapter (53 35 05) is used.

*** When you buy a new complete respirator or regulator with the new breathing tube QRS, it includes the adapter 53 05 06, needed for connecting the Speedglas welding helmet series 9000 and Speedglas visors to the new type of breathing tube.